

ATTACHMENT B

Bee Branch E. coli Monitoring Results

Sample	Date	Weather	Test 1 Ecoli (CFU/100mL)	Test 2 Ecoli (CFU/100mL)	Test 3 Ecoli (CFU/100mL)	Total Average Ecoli (CFU/100mL)	Location Description	Map Location Number
1	6/5	Partly Sunny	3200	3400	1400	2667	Carter Rd Det.	1
2	7/2	Sunny	1400	800	800	1000	Carter Rd Det.	1
3	7/30	Partly Sunny	2200	1200	1400	1600	Carter Rd Det.	1
4	4/24	Sunny	0	0	100	33	Carter Rd Det.	1
5	6/6	Sunny	800	600	200	533	Carter and 32nd	2
6	7/2	Sunny	400	1800	600	933	Carter and 32nd	2
7	7/30	Partly Sunny	200	600	600	467	Carter and 32nd	2
8	4/24	Sunny	0	0	0	0	Carter and 32nd	2
9	6/6	Sunny	0	0	0	0	W.32nd St. Det. Basin	3
10	7/2	Sunny	2000	2000	2000	2000	W.32nd St. Det. Basin	3
11	7/30	Partly Sunny	400	200	200	267	W.32nd St. Det. Basin	3
12	4/24	Sunny	0	0	0	0	W.32nd St. Det. Basin	3
13	6/6	Sunny	400	200	200	267	16th St Det. Basin	4
14	7/2	Sunny	0	0	0	0	16th St Det. Basin	4
15	7/30	Partly Sunny	2000	1000	1000	1333	16th St Det. Basin	4
16	4/24	Sunny	1000	1800	2000	1600	16th St Det. Basin	4